



The arrow shows the plated through hole that was intermittent. A piece of wire was inserted and soldered in place. The bad connection has now gone.